

## Condition of the work on the new Capitol at Albany, N.Y., photograph 45



A view of the construction of the second floor of the New York State Capitol building in Albany, New York, looking from the north front of the building. The photograph was taken on December 24, 1873.

**Identifier**

NYSA\_A1897-78\_45

**Alternate Identifier**

AMS Creator ID Number:

**Date**

December 24 1873

**Contributor**

Haines, Eugene S.M., 1833-1909 (Photographer)

**Repository**

New York State Archives

**Source**

New York State Archives. New York (State). Board of New Capitol Commissioners. Photographs of the new State Capitol during construction. A1897-78. Box 1, Image no. 45.

**Rights**

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

**More From This Series**

Photographs of the new State Capitol during construction

**Geographic Locations**

Albany (is associated with)