

Condition of the work on the new capitol at Albany, N.Y.



A view of the early construction of the New York State Capitol building in Albany, New York, taken on November 4, 1869. The photograph is labelled as number 12.

Identifier

NYSA_B0701-85_B2_F07

Alternate Identifier

DMS ID Number: 740

Date

November 4 1869

Contributor

Haines, Eugene S.M., 1833-1909 (Photographer)

Repository

New York State Archives

Source

New York State Archives. New York (State). New Capitol Commission. Capitol construction progress photographs. B0701-85. Box 2, Folder 7.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Capitol construction progress photographs

Geographic Locations

Albany (is associated with)