

## Condition of the work on the new Capitol at Albany, N.Y., photograph 18



A view of the early construction of the New York State Capitol building in Albany, New York, looking toward Swan Street and showing flooring laid. The photograph was taken on May 30, 1870.

### Identifier

NYSA\_A1897-78\_18

### Alternate Identifier

AMS Creator ID Number:

### Date

May 30 1870

### Contributor

Haines, Eugene S.M., 1833-1909 (Photographer)

### Repository

New York State Archives

### Source

New York State Archives. New York (State). Board of New Capitol Commissioners. Photographs of the new State Capitol during construction. A1897-78. Box 1, Image no. 18.

### Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

### More From This Series

Photographs of the new State Capitol during construction

### Geographic Locations

Albany (is associated with)