

Condition of the work on the new Capitol at Albany, N.Y., photograph 45



A view of the construction of the second floor of the New York State Capitol building in Albany, New York, looking from the north front of the building. The photograph was taken on December 24, 1873.

Identifier

NYSA_A1897-78_45

Alternate Identifier

AMS Creator ID Number:

Date

December 24 1873

Contributor

Haines, Eugene S.M., 1833-1909 (Photographer)

Repository

New York State Archives

Source

New York State Archives. New York (State). Board of New Capitol Commissioners. Photographs of the new State Capitol during construction. A1897-78. Box 1, Image no. 45.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Photographs of the new State Capitol during construction

Geographic Locations

Albany (is associated with)