

Canal Break at Forestport



Canal Break at Forestport. This is judged to be but a few hours after the banks were cut through on top, the water of canal still rushing through.

Identifier

NYSA_A0834-77_B5_F10

Alternate Identifier

DMS ID Number: 177432

Date

circa 1899

Contributor

C. Dayton (photographer)

Repository

New York State Archives

Source

New York State Archives. New York (State). Canal Investigating Commission (1898). Printed material, correspondence and photographs from the Canal Investigating Commission, 1888-1912. Series A0834-77, Box 5, Folder 10.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Printed material, correspondence and photographs from the Canal Investigating Commission

Geographic Locations

Oneida County (is associated with)