

Elizabethtown to Keene, parts 1 and 2



Crewman, a pick-up truck, cable shovel, and dump truck beside a rocky embankment at a road construction site in the Adirondacks (possibly Route 9N). The image is a construction progress photograph taken by the Dept. of Public Works, Bureau of Highways (related photograph file number 8663).

Identifier

NYSA_17672-92_B54_8663_3

Alternate Identifier

DMS ID Number: 170137

Date

July 23 1963

Contributor

Walsh, Frank M. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 54, negative no. 8663_3.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Essex County (is associated with)