

Pennsylvania Railroad, Elmira, NY



Railroad construction, possibly on South Main Street in Elmira. A crawler crane is digging up the street and several workmen and trucks are on site. A sign for Keefe Grocery Co. is on one of the buildings along the residential tree-lined street in the background. The project is associated with Public Service Commission number 3200. The image is a construction progress photograph taken by the Dept. of Public Works (related photograph file number 1031).

Identifier

NYSA_17672-92_B09_1031_001

Alternate Identifier

DMS ID Number: 171200

Date

October 15 1935

Contributor

Hart, F. J. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 9, photograph file 1031, negative 001.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Chemung County (is associated with)