

Exterior of Oxyozon Disinfecting Co. after fire



Windows are broken and boarded and wood charred after a fire in which a young girl burned to death at the Oxyozon Disinfecting Company located at 249 1/2 E. 13th St. in New York City. Debris lines the sidewalk and street. A note in "Photographs Taken by Factory Commission in 1912" suggests that the girl who died in this fire could have survived if there had been windows in the rear of the Oxyozon shop.

Identifier

NYSA_A3029-78_B3_F4

Alternate Identifier

DMS ID Number: 66243

Date

1912

Repository

New York State Archives

Source

New York State Archives. Factory Investigating Commission. Glass plate negatives and photographic prints of factory and housing conditions. 1911-1912. A3029-78, Box 3, Folder 4.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Glass plate negatives and photographic prints of factory and housing conditions

Geographic Locations

New York City (is associated with)