

Men's underwear factory: window to fire escape blocked



Interior of Union Mills, a men's underwear factory on Fulton St. in Hudson, New York. A worker stands at center. Machinery and other items block windows, including the ones to the left, which lead to a fire escape. The investigator noted that the windows lack sash weights and that the fire pail in the upper center hangs beyond reach.

Identifier

NYSA_A3029-78_B4_F2

Alternate Identifier

DMS ID Number: 66178

Date

1912

Repository

New York State Archives

Source

New York State Archives. Factory Investigating Commission. Glass plate negatives and photographic prints of factory and housing conditions. 1911-1912. A3029-78, Box 4, Folder 2.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Glass plate negatives and photographic prints of factory and housing conditions

Geographic Locations

Columbia County (is associated with)