

Men's underwear factory: large, unprotected machinery



Interior of cellar of Union Mills, a men's underwear factory on Fulton St. in Hudson, New York. Three men stand beyond an arched doorway next to large rolls of white cloth being fed into a machine. Overhead, large transmission belts less than six feet from the ground lack protective guards.

Identifier

NYSA_A3029-78_B4_F3

Alternate Identifier

DMS ID Number: 66259

Date

1912

Repository

New York State Archives

Source

New York State Archives. Factory Investigating Commission. Glass plate negatives and photographic prints of factory and housing conditions. 1911-1912. A3029-78, Box 4, Folder 3.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Glass plate negatives and photographic prints of factory and housing conditions

Geographic Locations

Columbia County (is associated with)