
Crooked Lake Canal Survey, Milo showing two views of Canal and Henderson



This is an ink, wash and charcoal map of a section of the Crooked Lake Canal in Milo. The map is split into two views. The first view shows a wide basin and an outlet stream. The second view shows, three bridges, twelve buildings, an unidentified road and an outlet stream branching off into mill runs. The red lines indicate courses and distances. The blue lines indicate canal right-of-way. The map also shows the property of Henderson.

Identifier

NYSA_A0848-77_MC7_DR14_V14_CRL_8

Alternate Identifier DMS ID Number: 150284

Date 1834

Repository New York State Archives

Source

New York State Archives, A0848-77, Canal System Survey Maps, 1832-1843, Map no. CRL-8

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our Copyright and Use Statement

More From This Series

Canal Commissioners canal system survey maps

Geographic Locations

Yates County (is associated with)