

## Erie Canal: NYCRR west of Rochester to South Greece



Contract 6. An image showing the failure of a flume and the volume of water being discharged into excavation from the flood. The image was taken from west of the Spoil Bank, opposite Station 2622.

**Identifier**

NYSA\_11833-97\_C006\_5643

**Alternate Identifier**

AMS Creator ID Number:

**Date**

April 1 1908

**Repository**

New York State Archives

**Source**

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 6, p. 76, negative 5643.

**Rights**

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

**More From This Series**

Barge Canal construction photographs