

Erie Canal: Locks and dams at Amsterdam and Tribes Hill



Contract 17. A photo of the excavation at west end of Lock 11 in Amsterdam taken by H.J. Richardson. The photo also shows the traveling derrick just starting.

Identifier

NYSA_11833-97_C017_2406

Alternate Identifier

AMS Creator ID Number:

Date

May 27 1907

Contributor

Richardson, H.J (Photographer)

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 17, p. 3, negative 2406.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs