
Oswego Canal: locks 5 and 6 and prism, Fulton to Oswego



Contract 37. A photo of the foundation of Dam 5, a result of line drilling in trench and depth of foundation.

Identifier

NYSA_11833-97_C037_2820

Alternate Identifier AMS Creator ID Number:

Date

May 15 1914

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 37, p. 54, negative 2820.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our Copyright and Use Statement

More From This Series

Barge Canal construction photographs