

Dockwall and grading, Little Falls



Terminal Contract 3. Looking east showing the dock wall and harbor at Little Falls. Dipper dredge is removing coffer-dam near east end of dock.

Identifier

NYSA_11833-97_TC003_00011

Alternate Identifier

Negative Numbers: 11

Date

June 1914

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Terminal Contract 3, p. 68, negative 11.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs