

## Dockwall, dredging, frame freighthouse, Flushing



Terminal Contract 43. Flushing. Shows bracing piles before being framed at easterly end of relieving platform of bulkhead wall.

### Identifier

NYSA\_11833-97\_TC043\_00007

### Alternate Identifier

Negative Numbers: 7

### Date

November 12 1920

### Repository

New York State Archives

### Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Terminal Contract 43, p. 78, negative 7.

### Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

### More From This Series

Barge Canal construction photographs