

## Water rushes through a break in the Forestport Feeder canal levee, 1899



Water rushing through a break in the Forestport Feeder canal levee, 1899. A crowd of onlookers oversee the water to the right. This levee, in upper Oneida County, broke several times over a period of a few years, raising suspicions of intentional sabotage.

**Identifier**

NYSA\_A0834-77\_B5\_F11

**Alternate Identifier**

**DMS ID Number:** 177203

**Date**

September 18 1899

**Contributor**

C. Dayton (photographer)

**Repository**

New York State Archives

**Source**

New York State Archives, New York (State). Canal Investigating Commission (1898). Printed material, correspondence and photographs from the Canal Investigating Commission, 1888-1912. Series A0834-77, Box 5, Folder 11.

**Rights**

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

**More From This Series**

Printed material, correspondence and photographs from the Canal Investigating Commission

**Geographic Locations**

Oneida County (is associated with)