

Effect of a break



Effect of a break. The men are pictured standing in bottom of canal. In front and below them is chasm torn by escaping water. Heavy timbers used to hold bank firm are shown in section of dike left by torrent.

Identifier

NYSA_A0834-77_B5_F13

Alternate Identifier

DMS ID Number: 177428

Date

1888 – 1912

Repository

New York State Archives

Source

New York State Archives. New York (State). Canal Investigating Commission (1898). Printed material, correspondence and photographs from the Canal Investigating Commission, 1888-1912. Series A0834-77, Box 5, Folder 13.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Printed material, correspondence and photographs from the Canal Investigating Commission

Geographic Locations

New York (is associated with)