

Little Valley, NY



Men spreading crusher run on a road under construction in rural Cattaraugus County, possibly NYS Route 353. In the foreground, a dump truck unloads the crusher near men with shovels; in the background a man operates heavy roller equipment. Cows are on a nearby hillside. The project is associated with Public Service Commission number 6035. The image is a construction progress photograph taken by the Dept. of Public Works (related photograph file number 486).

Identifier

NYSA_17672-92_B14_486_001

Alternate Identifier

DMS ID Number: 171377

Date

September 15 1933

Contributor

Hart, F.J. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 14, photograph file 486, negative 001.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Cattaraugus County (is associated with)