

Rock slide, Catskill Thruway



Cable shovel loading debris from a rock slide into a dump truck on a portion of the Catskill Thruway bordered by a steep rocky incline. Two workmen look on nearby. The image is a construction progress photograph taken by the Dept. of Public Works, Bureau of Operations and Maintenance (related photograph file number 5464).

Identifier

NYSA_17672-92_B34_5464_2

Alternate Identifier

DMS ID Number: 170042

Date

March 31 1951

Contributor

Timmers, Walter W. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 34, negative no. 5464_2.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Greene County (is associated with)