

Catskill Thruway Subdivision 5, Albany - Ravena



Workmen operating tractors, bottom dump trucks, and other heavy equipment owned by Grandview Construction Corp. of Mt. Vernon, NY, on a site for the NYS Thruway. The image is a construction progress photograph taken for the Dept. of Public Works, Bureau of Highways (related photograph file 5838).

Identifier

NYSA_17672-92_B36_5838_15a

Alternate Identifier

DMS ID Number: 170057

Date

June 24 1952

Contributor

Jasnieski, Stanley W. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 36, negative no. 5838_15A.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Albany County (is associated with)