

Catskill Thruway Subdivision 5, Albany-Ravena



Crane, workman, trucks, cars, equipment, and building materials at a NYS Thruway construction site. Image is a construction progress photograph taken by the Dept. of Public Works, Bureau of Highways, (related photograph file no. 6351).

Identifier

NYSA_17672-92_B39_6351_1

Alternate Identifier

DMS ID Number: 169616

Date

May 24 1954

Contributor

Dillon, Franklyn (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 39, photo file no. 6351.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Albany County (is associated with)