

Ticonderoga Bypass



A workman looks on as a cable shovel loads a dump truck with earth excavated from the construction site for the Ticonderoga Bypass or the NY 9N and NY 22 overlap. A bulldozer is also in view. The excavated site is in a wooded area. The image is a construction progress photograph taken by the Dept. of Public Works, Bureau of Highways (related photograph file number 8246).

Identifier

NYSA_17672-92_B52_8246_6

Alternate Identifier

DMS ID Number: 169672

Date

May 16 1962

Contributor

Walsh, Frank M. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 52, negative no. 8246_6.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Essex County (is associated with)