

South Glens Falls to Glens Falls Bridge



Workman using a crawler machine to pull road removal equipment over a roadway in a residential area of Glens Falls. A Sunoco gas station, customers, cars, a house, and a multi-story building are in the background. The image is a construction progress photograph taken by the Dept. of Public Works, Bureau of Highways (related photograph file number 8329).

Identifier

NYSA_17672-92_B53_8329_10

Alternate Identifier

DMS ID Number: 170136

Date

August 6 1962

Contributor

Walsh, Frank M. (photographer)

Repository

New York State Archives

Source

New York State Archives. Transportation and state facilities related photographs and photo logs, [ca. 1920-1980] New York (State). Dept. of Transportation. Graphic Arts Unit. Series 17672-92, Box 53, negative no. 8329_10.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Department of Transportation Graphic Arts Unit transportation and state facilities related photographs and photo logs

Geographic Locations

Saratoga County (is associated with)

Warren County (is associated with)