

Knitting mill: narrow aisles between machines in knitting room



Workmen stand in a room crowded with machinery at the Fulton Street plant of Union Mills, an underwear manufacturer in Hudson, New York. The aisles between machines are very narrow, creating fire and injury hazards. Belts and pulleys on machinery lack protective guards.

Identifier

NYSA_A3029-78_B4_F6

Alternate Identifier

DMS ID Number: 66267

Date

1912

Repository

New York State Archives

Source

New York State Archives. Factory Investigating Commission. Glass plate negatives and photographic prints of factory and housing conditions. 1911-1912. A3029-78, Box 4, Folder 6.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Glass plate negatives and photographic prints of factory and housing conditions

Geographic Locations

Columbia County (is associated with)