

Erie Canal: locks and dams at Scotia, Rotterdam and Cranesville



Contract 8. A photograph showing the spoil bank and a building looking west in Cranes Village [Cranesville?] that was taken by H.J. Richardson.

Identifier

NYSA_11833-97_C008_2708

Alternate Identifier

AMS Creator ID Number:

Date

May 16 1907

Contributor

Richardson, H.J. (Photographer)

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 8, p. 2, negative 2708.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs