

Erie Canal: locks and dams at Scotia, Rotterdam and Cranesville



Contract 8. A photograph showing a pile driver driving piles along the land wall, a shovel clearing up the excavation for a river wall, and an upper guide wall in distance in Cranes Village [Cranesville?].

Identifier

NYSA_11833-97_C008_2715

Alternate Identifier

AMS Creator ID Number:

Date

August 12 1907

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 8, p. 8, negative 2715.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs