
Oswego Canal: locks and prism at Fulton



Contract 10. A view looking north from Station 611+50 that shows the progress of rock excavation for Lock 2.

Identifier

NYSA_11833-97_C010_V1_0108

Alternate Identifier AMS Creator ID Number:

Date

January 2 1907

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 10, Volume 1, p. 8, negative 108.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our Copyright and Use Statement

More From This Series

Barge Canal construction photographs