

Erie Canal: dredging Oneida Lake to Mosquito Point; Lock 31



Contract 12. A view north showing a dipper dredge removing rock at the Orchard dam.

Identifier

NYSA_11833-97_C012_2796

Alternate Identifier

AMS Creator ID Number:

Date

June 30 1913

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 12, p. 83.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs