

## Erie Canal: Crescent to Rexford Flats; Mohawk river locks and dams



Contract 14. A photo showing the east gates damaged or breaking in the cofferdam at Lock 15 in Fort Plain.

**Identifier**

NYSA\_11833-97\_C014\_V2\_3341

**Alternate Identifier**

**AMS Creator ID Number:**

**Date**

November 27 1909

**Repository**

New York State Archives

**Source**

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 14, Volume 2, p. 30, negative 3341.

**Rights**

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

**More From This Series**

Barge Canal construction photographs