

Oswego Canal: locks 5 and 6 and prism, Fulton to Oswego



Contract 37. View east showing washout in west canal bank caused by high water, Minetto. State's Exhibit, No. A-23.

Identifier

NYSA_11833-97_C037_2751

Alternate Identifier

AMS Creator ID Number:

Date

April 4 1913

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract 37, p. 22, negative 2751.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs