

## Cayuga Seneca Canal Contract C: Locks, dams etc. at Seneca Falls



Contract C: Cayuga Seneca. Lock #6 showing leakage, lower paddles closed and upper paddle open.

**Identifier**

NYSA\_11833-97\_CaySen\_Contract\_C\_03082

**Alternate Identifier**

**Negative Numbers:** 3082

**Date**

June 3 1915

**Repository**

New York State Archives

**Source**

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Contract C., p. 85, negative 3082.

**Rights**

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

**More From This Series**

Barge Canal construction photographs