

Champlain Canal - Eastern Divison preliminary photograph



Contract: Miscellaneous Preliminary Champlain Canal - Eastern Divison. Stopping leaks on Glens Falls Feeder at "Jointa Lime Kilns". Done by Superintendent of Public Works, April 1905. HJR Photo.

Identifier

NYSA_11833-97_MP_Champ_East_01311

Alternate Identifier

Negative Numbers: 1311

Date

April 27 1905

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Miscellaneous Preliminary Champlain Canal - Eastern Division, p. 8, negative 1311.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs