

Pier at Gowanus Bay



Terminal Contract 55. East side of Gowanus Bay pier--Shows damage to side cap and short vertical posts. Cross clamps broken and pile pulled.

Identifier

NYSA_11833-97_TC055_00000_A15

Alternate Identifier

Negative Numbers: A-15

Date

February 11 1919

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Terminal Contract 55, p. 15, negative A15.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs