

Head house, West 53rd Street pier, New York City



Terminal Contract 225. Terminal 93. Headhouse under construction. Shows some windows that have been broken by boys. Also shows gravel pile of City tenant.

Identifier

NYSA_11833-97_TC225_00000_p024_2

Alternate Identifier

AMS Creator ID Number:

Date

May 19 1921

Repository

New York State Archives

Source

New York State Archives. New York (State). State Engineer and Surveyor. Barge Canal construction photographs. 11833-97. Terminal Contract 225, p. 24, no. 2.

Rights

This image is provided for education and research purposes. Rights may be reserved. Responsibility for securing permissions to distribute, publish, reproduce or other use rest with the user. For additional information see our [Copyright and Use Statement](#)

More From This Series

Barge Canal construction photographs